

Beam Schedule January - May 2014

		8 ⁰⁰ - 20 ⁰⁰	20 ⁰⁰ - 8 ⁰⁰			8 ⁰⁰ - 20 ⁰⁰	20 ⁰⁰ - 8 ⁰⁰			8 ⁰⁰ - 20 ⁰⁰	20 ⁰⁰ - 8 ⁰⁰
Mon	06.01	Weihnachten		Mon	03.02	Maintenance	Greubel (cont.)	Mon	03.03		
Tue	07.01	Maintenance	Hain	Tue	04.02		SNAKE p 20 MeV	Sat	01.03		
Wed	08.01		I ⁻²⁰ Au 10MV	Wed	05.02			Sun	02.03		
Thu	09.01		I ⁻²⁰ U 10MV	Thu	06.02			Mon	03.03		
Fri	10.01		I ⁻²⁰ Th 10MV	Fri	07.02			Tue	04.03		
Sat	11.01			Sat	08.02			Wed	05.03	Maintenance	Fabbietti
Sun	12.01			Sun	09.02			Thu	06.03		II ⁻¹⁰ p 10-20 MeV, 1-100 nA
Mon	13.01	Maintenance	Praktikum/LMU	Mon	10.02	Maintenance	Zimmer	Fri	07.03		
Tue	14.01		II ⁵⁰ ⁵⁸ Ni	Tue	11.02		CRESST ¹¹ B 61.5 MeV	Sat	08.03		
Wed	15.01	Praktikum/TU	II ⁻¹⁰ ⁵⁸ Ni	Wed	12.02			Sun	09.03		
Thu	16.01	Garrett	Q3D p ⁺ 22 MeV	Thu	13.02			Mon	10.03	Maintenance	Thirolf
Fri	17.01		Q3D d ⁺ 22 MeV	Fri	14.02			Tue	11.03		II ⁻¹⁰ p 7-18 MeV, <20 nA
Sat	18.01			Sat	15.02			Wed	12.03		
Sun	19.01			Sun	16.02			Thu	13.03		
Mon	20.01			Mon	17.02	Maintenance	Thirolf	Fri	14.03	Ruschke	I ⁻⁴⁰ p >22 MeV, 100 nA
Tue	21.01			Tue	18.02		Q3D p 25 MeV, 1 μA	Sat	15.03		
Wed	22.01			Wed	19.02			Sun	16.03		
Thu	23.01			Thu	20.02			Mon	17.03		
Fri	24.01			Fri	21.02			Tue	18.03		
Sat	25.01			Sat	22.02			Wed	19.03		
Sun	26.01			Sun	23.02	Maintenance		Thu	20.03	Maintenance	Bergmaier
Mon	27.01			Mon	24.02		Garrett	Fri	21.03		Q3D I 170 MeV
Tue	28.01			Tue	25.02		Q3D ¹² C 50 MeV, 1 μA	Sat	22.03		Q3D Au 40 MeV
Wed	29.01			Wed	26.02			Sun	23.03		
Thu	30.01			Thu	27.02			Mon	24.03		
Fri	31.01	Greubel	SNAKE p 20 MeV	Fri	28.02	Hain	I ⁻²⁰ Au 10 MV	Tue	25.03		
Sat	01.02			Sat	01.03		I ⁻²⁰ Th 10 MV	Wed	26.03		
Sun	02.02			Sun	02.03		I ⁻²⁰ U 10 MV	Thu	27.03	Gernhaeuser	II ⁻¹⁰ p 22 MeV, 1 nA

		8 ⁰⁰ – 20 ⁰⁰	20 ⁰⁰ – 8 ⁰⁰			8 ⁰⁰ – 20 ⁰⁰	20 ⁰⁰ – 8 ⁰⁰			8 ⁰⁰ – 20 ⁰⁰	20 ⁰⁰ – 8 ⁰⁰
Fri	28.03	Gernhaeuser	II ⁻¹⁰ p 22 MeV, 1 nA	Fri	25.04		I ⁻²⁰ Au 10 MV	Thu	22.05		
Sat	29.03			Sat	26.04			Fri	23.05		
Sun	30.03			Sun	27.04			Sat	24.05		
Mon	31.03	Maintenance	Reichart	Mon	28.04			Sun	25.05		
Tue	01.04		SNAKE p 20 MeV	Tue	29.04	Maintenance	Greubel	Mon	26.05		
Wed	02.04			Wed	30.04		SNAKE C 55 MeV	Tue	27.05		
Thu	03.04			Thu	01.05			Wed	28.05		
Fri	04.04	Ludwig	GAMS ⁵⁴ Fe 12 MV	Thu	01.05			Thu	29.05		
Sat	05.04			Fri	02.05			Fri	30.05		
Sun	06.04			Sat	03.05			Sat	31.05		
Mon	07.04			Sun	04.05						
Tue	08.04	BeamtimeMeeting	Ludwig (cont.)	Mon	05.05						
Wed	09.04		GAMS ⁵⁴ Fe 12 MV	Tue	06.05						
Thu	10.04	Maintenance	Thirolf	Wed	07.05						
Fri	11.04		I ⁻⁴⁰ p 20 MeV, 100 nA	Thu	08.05						
Sat	12.04			Fri	09.05						
Sun	13.04			Sat	10.05						
Mon	14.04	Chiang	I ¹⁰ I 80 MeV, 800 nA	Sun	11.05						
Tue	15.04			Mon	12.05						
Wed	16.04			Tue	13.05						
Thu	17.04			Wed	14.05						
Fri	18.04	Ostern		Thu	15.05						
Sat	19.04			Fri	16.05						
Sun	20.04			Sat	17.05						
Mon	21.04			Sun	18.05						
Tue	22.04	Chiang (cont.)	I ¹⁰ I 80 MeV, 800 nA	Mon	19.05						
Wed	23.04			Tue	20.05						
Thu	24.04	Maintenance	Schönert	Wed	21.05						